Sanitized Copy Approved for Release 2011/09/20 : CIA	1-RDP78-03424A002400090025-1 FCS Feli Feli Feli
Chief, Internal Projects Section	13 February 1957
Chief, External Projects Section	25X1
RR-11AA/SD Transistorized Receiver	
ments at found to be within acceptable limits. such information available to us at a indicate that something within the se problem. Several tests have been run but such tests are so limited in stat conclusions can be deduced. 3. has asked that we run available to us and submit the result particularly interested in determinin runs on any given set. Also, it has be made as the test point is approach will permit correlation of all tests 4. It has been suggested that i caused by the "set" of cament used in screws in setting the profile cam, or profile cam itself. Such a change co tuning of the receiver. Another poss adjustment of the padder condenser lo of the tuner mechanism. has a condenser to bring the receiver close running any checks on the unit.	inser, stated that the test instri ²⁵ X1 the tuner units) had been checked and 25X This information contradicted in earlier date, and seemed to et itself is the cause of the contradicted in on the units still at Philoo, existical evidence that no concrete is a series of tests on each unit 25X1 is to them for analysis. They are use the repeatability of calibration been suggested that all checks ned from the low side. This between the various laboratories. The incorrect calibration may be a fixing the location of the may be a change in "set" of the could be brought about by repeated sible answer seems to lie in the located on the oscillator panel suggested we readjust this 25X1 to correct calibration before
4, 5, 10 and 12 are forwarded in a se	parate package.
	25X1 OC-E/R&D-EP/FCS:mjr (12 Feb. 57)
APPRO(m=7).	OC-E/R&D-EP/FCS:mjr (12 Feb. 57) cc: R&D Subject File/OC-E/Rea 25X1 Chrono/Dev-ep
Chief, Research & Development Branch	(will go itet in 3/18.

Sanitized Copy Approved for Release 2011/09/20 : CIA-RDP78-03424A002400090025-1